F-GW709





3





ATTENTION:
TO AVOID EXCESSIVE FORCE, WHEN YOU ASSEMBLED LIKE PICTURE TWO, IT IS THE RIGHT POSITION, DO NOT TURN SCREW ANY MORE





| Α | | 1 |
|----|----------------|---|
| В | | 1 |
| B1 | | 1 |
| D1 | / | 4 |
| С | | 4 |
| D | 0 | 4 |
| Е | • | 4 |
| F | | 4 |
| G | | 1 |
| Н | (%) (0) | 2 |
| I | % | 1 |

